

Badger Detector Test

7500 p Mag Meter

Note:

Before performing function test you must power unit down.

Measure across the two coil inputs. Red And Blue wire.

40 OHMS

Measure each coil to ground. Red to Green and Blue to Green.

Open – No Resistance on empty pipe

Measure Electrodes to ground with full pipe of liquid.

Black to green and white to green.

High resistance. Above 300 ohms